




car-pdi-check



Comprehensive Car Inspection Report



Thorough inspection with
300+ quality checks



Precise insights from
experienced technicians



Trusted by
Over 5000+ customers



5228+

Inspection
Completed

25+

Cities
Available

4.7+

Average
Rating



Vehicle Details

Vehicle Name	: ERTIGA CNG
Vehicle Manufacturer	: MARUTI SUZUKI
PDI Location	: SOLAPUR
Date of PDI	: 04/07/2026
Vehicle MFG Date	: 2026 APRIL
Tyre Batch	: MATCHED (1226)
VIN Number	: MA3BNC62STDC81391
KM Driven	: 021.7 KM
Name of the Evaluator	: SOPAN .B

**OVERALL RATING
OF THE INSPECTED
VEHICLE**

5 / 5

RECOMMENDATIONS :

- COOLANT LEVEL IS LOW AND NEEDS TO BE FULL BEFORE THE TIME OF DELIVERY.



Inspection Summary

This section provides a comprehensive evaluation of the most recent car assessment, meticulously divided into five key categories to offer an in-depth and accurate overview

Exterior

We have inspected your vehicle's exterior and found that it is in overall good condition, no major damages or structural issues were observed during the inspection.

5 / 5

Engine & Transmission

The engine and transmission systems were checked and found to be in perfect working condition.

5 / 5

Steering, Suspension & Brakes

Your car's steering, suspension, and brakes are all in good condition. There are no issues that were founded.

5 / 5

Air Conditioning

The air conditioning in your car is working perfectly. The AC, heater, and climate control are all functional.

5 / 5

Electricals & Features

Your car has all the electrical features working well, including power windows, airbags, music system, and a reverse camera.

5 / 5

Interiors

Vehicle's interior is in perfect and no issues or irregularity founded during the inspection.

5 / 5

Tyres

All the four tyres and one stepny tyre is in perfect condition and no irregularity founded during the inspection.

5 / 5

Exterior Panels

The bonnet, doors, rear door, fenders, and running board are all in factory-standard condition. No issues or irregularities were observed during inspection.

5 / 5

Vehicle Images

EXTERIOR / BODY & STRUCTURE :












INTSTRUMENT CLUSTER :



RO & VALID TAGS:






TYRES :



TYRE BATCH :





LIGHTS / OTHER FEATURES :









**Left Side Door Mirror
Indicators Working**



**Right Side Door Mirror
Indicators Working**

**Left Side Parking Sensors
Working**



**Right Side Parking Sensors
Working**



Car A /c Panel Working Properly



Car Glove Box Working







**All Power Windows Switches
Working Properly
Mirror Switches Working
Door lock / Unlock Button
Working Properly**



**Both Side Type C Charging
Port's Working**







Front Side Roof Light Working



Rear Side Roof Light Working

**Rear Left Door Latch Working
Power Window Switch
Working Properly**



**Rear Right Side Door Latch
Working
Power Mirror Switch Working**



**Front Left side Door Latch
Power Windows Switch
Working**



**Left Side Front Side Door
Latch Working
Power Windows Switch
Working**



Rear A/c Vent Working Properly



Rear A/c Fan Button Working Properly




Car Infotainment system Working Properly





ENGINE & TRANSMISSION :






TOOL KIT / STEPNY :



Car Jack Available




Spair Tyre Ok

DOORS EXTERIOR :




>>> VIN NUMBER :



>>> INFOTAINMENT/CAMERA SYSTEM :



UNDER BODY :







BATTERY :



BOOTSPACE :



OVRMS :



STEERING WHEEL :



TEMPERATURE METER READINGS :

A/c Temperature Ok



PHYSICAL REPORT :

CAR PDI expert CAR-PDI-CHECK.COM

PRE DELIVERY INSPECTION (PDI) REPORT 17

CUSTOMER NAME Chinna Govardhan Charyundi
DATE: 04-06-2026
YEAR/MODEL: Maruti Celerio - Vxi CNG
MILAGE: Colour - white
RO TAG: _____


CHECKED AND OKAY AT THIS TIME

MAY REQUIRE FUTURE ATTENTION

REQUIRED IMMEDIATE ATTENTION

EXTERIOR CHECKS

1. BODY PAINT - NO SCRATCHES/DENTS
2. ALL DOORS/BONNET/BOOT OPEN & CLOSE PROPERLY
3. WINDSHIELD & GLASS
4. LIGHTS (HEAD/TAIL/INDICATORS) FUNCTION
5. ANTENNA/ROOF RAILS FITTED PROPERLY
6. CHECK PAINT FINISH CONSISTENCY ON ALL PANELS
7. CHECK ALIGNMENT OF ALL DOORS AND PANELS
8. TEST ALL EXTERIOR LIGHTS (HIGH BEAM/LOW BEAM)
9. CHECK FUEL CAP AND FLAP OPERATION
10. INSPECT UNDERBODY FOR DAMAGE OR RUST
11. CHECK WHEEL ALIGNMENT VISUALLY
12. CHECK DOOR SEALS FOR PROPER FITTING
13. CHECK WINDSHIELD WASHER FUNCTION
14. CHECK HORN LOUDNESS
15. REVERSE CAMERA/SENSORS FUNCTIONING
16. FINAL ROAD TEST CONDUCTED
17. CAR CLEANED AND POLISHED
18. SUNROOF OPERATION (IF AVAILABLE)
19. DEFOGGER FUNCTIONALITY




INTERIOR CHECKS

1. SEAT UPHOLSTERY CLEAN AND INTACT
2. DASHBOARD SWITCHES WORKING
3. CABIN LIGHTS WORKING
4. POWER WINDOWS/DOOR LOCKS
5. REAR-VIEW & SIDE MIRRORS ADJUSTABLE
6. SEAT BELTS OPERATIONAL
7. ODOMETER READING WITHIN RANGE (2) km
8. REMOTE KEY/CENTRAL LOCK
9. DASHBOARD WARNING LIGHTS
10. GLOVE BOX & COMPARTMENTS
11. POWER OUTLET/USB PORTS
12. INFOTAINMENT SCREEN CLARITY
13. ALL SPEAKERS WORKING
14. CLOCK/TIME SETTINGS
15. REMOTE BOOT RELEASE




1. STEERING TILT/TELESCOPIC
2. CENTRAL LOCKING (MANUAL & REMOTE)
3. FLOOR MATS INSTALLED
4. MUD FLAPS INSTALLED
5. FIRST AID KIT & WARNING TRIANGLE
6. INTERIOR POLISH CLEAN AND ODOR-FREE
7. INFOTAINMENT/BLEETOOTH SYSTEM




AC

1. AC/HEATER FUNCTIONING PROPERLY ✓
2. CABIN AIR FILTER CONDITION ✓
3. AC VENT AIRFLOW ✓
4. DIRECTION CONTROL OF AC VENTS ✓
5. AC COOLING EFFICIENCY ✓



TYRE & WHEEL AREA

1. TYRES - CONDITION & PRESSURE ✓
2. SPARE TYRE PRESENT ✓
3. TYRE TREAD DEPTH ✓
4. WHEEL NUT TORQUE ✓
5. WHEEL ALIGNMENT ✓
6. TOOLKIT, JACK, AND SPANNER ✓



Internal Parts of Suspension



Suspension System



BATTERY & ELECTRICAL

1. BATTERY TERMINAL CONNECTED PROPERLY ✓
2. BATTERY VOLTAGE (IF MEASURED) ✓
3. POWER TO INFOTAINMENT/DASHBOARD ✓
4. CABIN ELECTRICAL PORTS WORKING ✓
5. NO BATTERY-RELATED WARNING LIGHTS ✓



ENGINE & MECHANICAL

1. ENGINE OIL LEVEL CORRECT ✓
2. COOLANT LEVEL ADEQUATE ✓
3. BRAKE FLUID LEVEL ADEQUATE ✓
4. NO VISIBLE LEAKS IN ENGINE BAY ✓
5. ENGINE CRANKING/START SMOOTH ✓
6. IDLING & SOUND NORMAL ✓
7. RADIATOR FAN WORKING ✓
8. BELTS & HOSES INTACT ✓
9. ENGINE MOUNT VIBRATIONS MINIMAL ✓



DOCUMENTATION

1. OWNER'S MANUAL INCLUDED ✓
2. WARRANTY CARD INCLUDED ✓
3. INVOICE PROVIDED ✓



1. INSURANCE PAPERS READY ✓
2. TEMPORARY REGISTRATION READY ✓




END OF THE REPORT

CNG CYLINDERS :





Thank you for choosing us!




We truly appreciate your decision to prioritize the safety and maintenance of your vehicle. By opting for a thorough inspection, you're ensuring not only the longevity of your car but also peace of mind for you and your loved ones.

Should you have any questions about the inspection report or need further assistance, please don't hesitate to reach out. We're here to help and ensure your vehicle remains in top condition.

Thank you once again for your trust and patronage.



www.car-pdi-check.com



THIS REPORT CANNOT BE USED FOR LEGAL PURPOSES



9421762760



CAR_PDI_CHECK



car-pdi-check.com